


NOTES:

INTERNAL GROUTING WORKS BEST WHEN THE JOINT LEAK IS CAUSED BY INADEQUATELY CONSOLIDATED CONCRETE AROUND THE WATERSTOP. IT IS LESS EFFECTIVE WHEN THE LEAK IS CAUSED BY WATERSTOP TEARS OR POOR SPLICING. SUITABLE INJECTION GROUT WOULD BE:

- ADCOS PURINJECT® 1C DUO
- ADCOS PURINJECT® 1C FLEX
- ADCOS PURINJECT® 1C FLEX 55
- ADCOS PURINJECT® HYDROFOAM
- ADCOS ACRYLINJECT® AC FLEX



DATE	08/23/2024
DRAWN_BY	D.J.I.
SCALE	N.T.S.
PRODUCT_NUMBER	VARIES

**STANDARD FAILED WATERSTOP DETAIL**

DRAWING\_TITLE

